SUNSTAR传感与控制 http://www.sensor-ic.com/ TEL:0755-83376549 FAX:0755-833761&2 pEtM&IL:pags

TPT300V IR Pyrometer



- Contact less Temperature
 Measurement
- High Accuracy
- Wide Temperature Range
- Digital and Analogue Interface
- Industrial Usage (IP65)

DESCRIPTION

TPT 300 is a contact-less temperature measuring system - called pyrometer - based on the detection of infrared radiation.

TPT 300 is equipped with a lens and an infrared sensor (Thermopile) in front. It has to be pointed at the target object.

The basic working principle is:

- Detection of infrared radiation with a Thermopile sensor
- Further analogue signal processing
- Calculation of the objects temperature using a microcontroller
- Providing the objects temperature at digital or analogue output

The main fields of applications are temperature measuring in industrial applications i.e. at moving or inaccessible parts.

FEATURES

APPLICATIONS

- 0°C 300°C Measurement Range
- 9V 24V Supply Voltage Range
- RS232 Interface & Analogue Voltage Output
- IP65 protected

- Contact less Temperature Measurement
- Industrial Process Control

ABSOLUTE MAXIMUM RATINGS

Absolute maximum ratings are limiting values of permitted operation and should never be exceeded under the worst possible conditions either initially or consequently. If exceeded by even the smallest amount, instantaneous catastrophic failure can occur. And even if the device continues to operate satisfactorily, its life may be considerably shortened.

measure

Parameter	Symbol	Conditions	Min	Тур	Max	Unit
Supply Voltage	Vcc	Measured versus GND	-1		30	V
Storage Temperature	Tstor		-20		85	°C

OPERATING CONDITIONS

Parameter	Symbol	Conditions	Min	Тур	Max	Unit
Supply voltage	Vcc	Measured versus GND	9		24	V
Emission Coefficient	3	Adjustable via RS232	0.1		1	


OPERATING CONDITIONS

Parameter	Symbol	Conditions	Min	Тур	Max	Unit
Field of View	FOV			±5		0
Spectral Sensitivity	S			814		μm
Supply Current	I	Full ambient temp. range, no output load		22		mA
Digital Output Rate					10	Hz
Digital Output Settings				Baud, arity, 1 Bit		


OPERATIONAL CHARACTERISTICS

Parameter	Symbol	Conditions	Min	Тур	Max	Unit
Object Temperature Range	Tobj		0		300	°C
Ambient Temperature Range	Tamb		0		85	°C
Accuracy of Target Temp. Measuring		Tambient = 25°C	± 1% of Full Scale Range resp. ± 3°C			
Accuracy of Target Temp. Measuring		Full ambient temp. range	± 1.5% of Full Scale Range resp. ± 4.5°C			
Resolution Digital			0.3		°C	
Analog Output Characteristics			T[°C] x 5V/300°C		V	
Analog Output Range			0.2 – 4.8		V	
Resolution Analog				0.3		°C
Analog Output Source Resistance				40		Ω
Housing			Stai	inless s	teel	
Protection class				IP 65		

MECHANICAL DIMENSIONS



TERMINALS



Binder connector series 712

DSUB 9 connector (female)

measure

Please take care: pin numbers are marked on the Binder and on most DSUB connectors!

Pin	Symbol	Description	Тур
1	+VS	Supply Voltage	Supply
2	GND	Ground potential	Supply
3	NC		
4	NC		
5	AN	Analog Output (Voltage, Current)	Analog Output
6	RX/A	Receive Data (RS232)	Digital Input/Output
7	TX/B	Transmit Data (RS232)	Digital Input/Output

FUNCTION

RS232 SETTINGS

The port settings are fixed at:

Parameter	Setting
Baudrate	9600
Data Bits	8
Parity	None
Stopp Bits	1

TPT MODES

There are two modes implemented in TPT sensors: the Free Running mode and the On Request mode. In the Free Running mode the sensor cyclically sends measuring results via RS232. In this mode no further

meas

communication (for instance changing sensor parameters) is possible. The only telegram which is accepted in this mode is the "Set On Request Mode" telegram, which stops sensor output.

In On Request mode the sensor only sends data via RS232 after user has sent any request telegram. Only in this mode the changing of sensor parameters is possible.

NOTE: Updating the analog output is directly correlated with updating the RS232 output. Only if output data are sent via RS232 the analog output is updated. Two cases are possible: the "Request Result Data" telegram causes updating serial and analog output and - on the other hand - the cyclically sending data in Free Running Mode.

PROTOCOL DEFINITION

REQUEST SOFTWARE VERSION AND SERIAL NUMBER

User System → TPT Sensor	TPT Sensor → User	Notes				
"V"	<version and="" number="" serial=""></version>	ASCII- Format				
<version and="" number="" serial=""> is given as follows:</version>						
HL-Planartechnik TPT V2.1 041	14001-2 <cr> <lf></lf></cr>					
HL-Planartechnik	manufacturer company					
TPT	product family (pyrometer)					
V2.1	software version					
0414001-2	serial number, format: yy v which means: year (2 digit week of year (2 digits), consecutive number in the product code ("2" is the co	s), week (3 digits),				
<cr> <lf></lf></cr>	carriage return, linefeed					



Set "Free Running" Mode		
User System → TPT Sensor	TPT Sensor → User	Notes
"F"	"F" Echo	ASCII- Format

Free Running Mode means, that result data is cyclically updated at analog and digital output.

measurer

Set "On Request" Mode		
User System → TPT Sensor	TPT Sensor → User	Notes
" f "	"f" Echo	ASCII- Format

On Request Mode means, that the sensor only sends data, if the user has sent any request telegram before.

SET OUTPUT FORMAT

Set "Format Object and Ambient Temperature"					
User System → TPT Sensor TPT Sensor → User Notes					
"["	"I" Echo	ASCII- Format			

Set "Format Object Temperature"					
User System → TPT Sensor TPT Sensor → User Notes					
"i" "i" Echo ASCII- Format					

SET EMISSIVITY FACTOR

Step	User System → TPT Sensor	TPT Sensor → User	Notes
1	"e"	"e" Echo	ASCII- Format
2	<emissivity></emissivity>	<emissivity> Echo</emissivity>	Binary- Format

Emissivity is adjustable in range of 1 – 100 %. Parameter <emissivity> must be given as one-byte integer value. For instance: E=100% corresponds to 64hex respectively ASCII "d".

READ EMISSIVITY FACTOR

Step	User System → TPT Sensor	TPT Sensor → User	Notes
1	"E"	"E" Echo	ASCII- Format
2	<emissivity></emissivity>	<emissivity> Echo</emissivity>	ASCII- Format



User System → TP	T Sensor T	PT Sensor → User	Notes
"R"	<	Result Data>	ASCII- Format

measu

There are two output formats available.

If "Format Object and Ambient Temperature" is selected, the <Result Data> is given as follows:


+255:+784 <cr> <lf></lf></cr>	
+255	sensor temperature in tenth of degree C
:	colon (delimiter)
+784	object temperature in tenth of degree C
<cr> <lf></lf></cr>	carriage return, linefeed

If "Format Object Temperature" is selected, the <Result Data> is given as follows: +784 <CR> <LF> +784 object temperature in tenth of degree C <CR> <LF> carriage return, linefeed

CE CONFORMITY

The sensor meets the normative requirements for use in industrial environment. The complete compliance with the norm is given under following conditions:

- Housing is connected to PE by screws
- HL connecting cable is used
- Shield is connected to GND at user side



If the user intends to employ his own connecting cable, it is recommended to equip this cable with a ferrite near the sensor. A suitable type is Würth #74271112.

ORDERING INFORMATION

The information in this sheet has been carefully reviewed and is believed to be accurate; however, no responsibility is assumed for inaccuracies. Furthermore, this information does not convey to the purchaser of such devices any license under the patent rights to the manufacturer. Measurement Specialties, Inc. reserves the right to make changes without further notice to any product herein. Measurement Specialties, Inc. makes no warranty, representation or guarantee regarding the suitability of its product for any particular purpose, nor does Measurement Specialties, Inc. assume any liability arising out of the application or use of any product or circuit and specifically disclaims any and all liability, including without limitation consequential or incidental damages. Typical parameters can and do vary in different applications. All operating parameters must be validated for each customer application by customer's technical experts. Measurement Specialties, Inc. does not convey any license under its patent rights nor the rights of others.

measurem