

SSI Technologies – Application Note PS-AN18

MediaGauge™ Series MG & MG1 & MGA

User's Guide



MG Series MediaGauge™



MG1 Series MediaGauge™



MGA Series MediaGauge™

ON/UNIT/OFF

- Press **ON / UNIT / OFF** to turn unit on.
- Press again when the unit is on to change the unit of measure from PSI, BAR or MPA.
- Hold the **ON / UNIT / OFF** for three seconds and release to turn the unit off.

LIGHT/P-H

- Press the **LIGHT / P-H** to turn on the back light.
- Hold the **LIGHT / P-H** for three seconds to display the maximum pressure that the device has measured.
 - "OL" is greater than the maximum range of the unit. The maximum number will be blinking.
- Hold the **RESET / CLEAR** button for three seconds to clear the maximum number.
- Hold the **LIGHT / P-H** button for three seconds to go back to the normal display.

RESET/CLEAR

- In a normal function if you press the **RESET/CLEAR** the display will not change.
- If you hold the **RESET/CLEAR** for three seconds it will reference the gauge to whatever pressure is currently applied to the unit.
 - {For example; if you have 20psi on the display and you hold down **RESET/CLEAR** then the display will show 0.0 and a measurement of 30psi would then read as 10psi on the display.}
- Hold **RESET/CLEAR** for three seconds to reset unit to original setting. Unit must be disconnected or have an input of 0psi.